

State of Utah DEPARTMENT OF NATURAL RESOURCES Division of Oil, Gas & Mining

MICHAEL R. STYLER Executive Director JOHN R. BAZA
Division Director

Inspection Report Minerals Regulatory Program

March 20, 2007

Supervisor

Permit number: M/043/017

Time 8:40 am

Inspection Date: March 20, 2007

Mine Name: Brown's Canyon Rock Quarry Operator Name: Rock Products of Utah, Inc...

Inspector(s): Dan Smith and Lynn Kunzler, DOGM Other Participants: Tony Martin and Develon Worth

Mine Status: Active

	Elements of Inspection	Evaluated	Comment	Enforcement
1.	Permits, Revisions, Transfer, Bonds	\boxtimes		
2.	Public Safety (shafts, adits, trash, signs, highwalls)	$\overline{\boxtimes}$		
3.	Protection of Drainages / Erosion Control	\boxtimes		
4.	Deleterious Material		\boxtimes	
5.	Roads (maintenance, surfacing, dust control, safety)			
5.	Concurrent Reclamation			
7.	Backfilling/Grading (trenches, pits, roads, highwalls,			
8.	Soils			
9.	Revegetation			

Purpose of Inspection:

10. Other

Routine inspection while in the area.

Inspection Summary:

Upon arrival at the site, it was noted that a new scale and scale house have been constructed along the western access road. The scale was sitting on a concrete pad and had concrete approaches. Inspectors were told that this was added in January of 2007 (the Division had not received an amendment for this structure).

The disturbed area was surveyed with the GPS to determine total acreage disturbed. Visually it appeared that he was close, if not over the permitted disturbed area.

Several barrels labeled 'Used Motor Oil' were located near the center of this project. One of the barrels had a small amount of oil spilled on the top and surrounding ground. Mr. Martin had indicated that MSHA had conducted an inspection last week and had them remove the barrels from where they had originally been stored (with spill containment) due to close proximity of welding equipment (this was in violation of MSHA regulation). Mr. Worth indicated that the barrels would be removed from the site by the end of the day.

Photos were taken to document site conditions.

Conclusions and Recommendations:

Notice of Violation # MN-07-01-01 was issued for installing the scales and scale house (not following the approved plan) prior to submitting and amendment and receiving approval from the Division. Abatement requires the operator to submit an amendment (w/map showing location) by April 10, 2007.

Inspection Date: March 20, 2007

Page 2 of 2 M/043/017

The results of the GPS survey showed a total of 20.18 acres disturbed. Not all of the permitted area is disturbed, but there are small areas outside the permit area that have been disturbed. During the inspection, Mr. Worth recognized that he was close to the disturbance limit of his permit and discussed plans to add about 20 acres to his permit. It is recommended that a letter go to Mr. Worth requesting this amendment by May 30, 2007, and that his amendment includes all the current disturbed areas.

Continue to monitor this site when in the area.


Inspector's Signature

LK:pb

Attached: GPS Map of current disturbance.

Cc: Develon Worth, Operator w/attachment

O:\M043-Summit\M0430017-BrownsCynRock-RockProducts\inspections\Insp-03202007.doc



Mine Number: M0430017 Mine Name: Brown's Canyon Rock Quarry Township 01 S Range 05 E Section 20 SLBM

Inspection Date Mar. 20, 2007 Map Produced by DKS Acres Disturbed 20.18
Acres Seeded 0
Road Acres Disturbed 0


Acres Released 0
Acres Excluded 1.2
Acres PreExisting 0

20.18


Total Acres Distrubed

Legend All items symbolized in legend may not be appear on map

Acres Prelaw



DOQ imagery date 2006





V Sept. of Natural Resources Division of Oil, Gas, and Mining Mineral Mines Program

Feet
1:2,100 1 inch equals 175 feet
Verify Scale
Different data sources and input scales
may cause misalignment of data layers.
This product may not meet DOGM
standards for accuracy and content.